WARNING!!!

DO NOT SIGN THE DELIVERY RECEIPT!!!

UNTIL YOU DO THE FOLLOWING

It is your responsibility to check the shipment thoroughly.

- <u>COUNT ALL BOXES</u> to confirm that it matches the number indicated on the delivery receipt.
- 2. <u>INSPECT THE OUTSIDE OF EVERY BOX</u> for signs of damage. Read and follow warning labels and instructions. Examples: Holes, crushed corners, wrinkles, black rub marks, cardboard that looks to have been pushed or hit. Broken pallets and rattling boxes are all possible signs of damage. <u>Make note of any such problems on delivery receipt</u> before signing.
- 3. Note all damage on delivery receipt in detail, <u>BEFORE THE DRIVER LEAVES</u>.
- 4. <u>CALL SHIPPER IMMEDIATELY (1-800-523-1958)</u> with the information so we can help you determine if you should refuse delivery or we can supply parts to correct the problem.
- 5. If an item looks to be damaged more than you believe you can repair, then refuse it and notify us so we can get another one shipped asap to you.

*** IF YOU SIGN FOR YOUR DELIVERY FREE AND CLEAR OF ANY DAMAGE IT WILL BE YOUR RESPOSIBILITY TO FILE CLAIMS WITH THE CARRIER FOR CONCEALED DAMAGE. ***



Portable sign crated and ready for shipment.



Tip N Tell – This indicator is on the outside of every crate.